



# LABOR – ASTER

## INDUSTRIAL AUTOMATION



Certyfikat nr QS/14/07



AC 083  
QMS

## TWO-WIRE RESISTANCE CONVERTER type R-S3

- Measurement of resistance or potentiometer position
- All circuits mutually separated
- Compensation of line resistance change – three or four-wire sensor connection
- Control of output 4...20mA current loop

### APPLICATION:

Two-wire converter **R-S3** is design to convert resistance changes of a sensor to current 4...20mA signal. Output current signal can be converted to voltage signal by using external 250Ω resistor. The converter provides galvanically separation of input and output circuits. Using separation eliminates any influence of plant interferences to cooperation with data collection system, recorder.

The converter can be used as:

- linear conversion of resistance changes:  
 $f = k * \Delta R,$
- linear conversion of temperature changes for resistance sensors  
 $f = k * \Delta T,$
- conversion of potentiometer position

**The R-S3 converter, when using three-wire sensor connection, provides total compensation of the influences of line parameters changes to measurement results.**

When requested the converter can be made in version for four-wire connection of a sensor.

The user can correct the settings of the beginning and the gain with potentiometers “ZERO” and “SPAN” placed in the front panel.

### BASIC TECHNICAL PARAMETERS

Input signal:

- resistance changes  $\Delta R$  - 1...10 000Ω
- Pt100, Ni100 -  $\Delta T_{min}=20^{\circ}C$
- Pt500 -  $\Delta T_{min}=5^{\circ}C$
- Pt1000 -  $\Delta T_{min}=2.5^{\circ}C$


potentiometer position -  $\Delta R_{min}=1\Omega$

Output signal - current loop 4...20mA supplied from the outside with voltage  $U_z$


Supply voltage  $U_z$  of the current loop 4...20mA - 12...36V

Sensor measurement current - 0,4mA


Load resistance - max 600Ω for  $U_z=24V$   
 $R_{load}=(U_z-12V)/20mA$




Class	- 0,1%
Nonlinearity	- 0,1%
$f = k * \Delta R$	- $\pm 0,05\%$
$f = k * \Delta T$	- $\pm 0,1\%$
Possible linearization	- any non-linearity
Temperature drift	- 0,01%/°C
$\Delta R > 10\Omega$	- 0,02%/°C
$\Delta R \leq 10\Omega$	- 0,02%/°C
Error due to load resistance and supply $U_z$ changes	- $\pm 0,02\%/V$
Time constant	- 0.1s or as agreed: 0,05...1s
Sensor connection	- 2-, 3-, or 4-wire line
Line resistance	- 2-wire - $\leq 5\%$ of range $\Delta R$ 3- or 4-wire - $\leq 30\Omega$ one wire
Galvanic separation	- between input and output circuits
Isolation voltage test	- 2kV, 50Hz or equivalent
Measurement ranges	- as agreed
Rail housing	- width 22.5 mm height 79 mm depth 74 mm
protection level	- IP40
mounting	- universal rail clamp
Safety requirements	PN-EN 61010-1:2002
EMC requirements	PN-EN 61000-6-1 PN-EN 61000-6-3



Diode allowing measuring output current is unavailable for version with 4-wire input.



Load resistance calculation method



Achieving voltage output signal method

### HOW TO ORDER:

L - rail housing  
P - wall housing

4 - four-wire sensor connection

Input range


P1...P23 - sensor Pt according to table 1

N1...N11 - sensor Ni according to table 2

$R_{min}/R_{max}$  - min/max value of potentiometer resistance

L - with linearization

BL - without linearization



**Order example:** two-wire resistance converter, input Pt100, range 0...200°C, linearization type: R-S3-L-P7-L

### Working conditions:

- Ambient temperature - storing: -30°C...+60°C
- Ambient temperature - working: -25°C...+60°C
- Relative humidity: max 90%, no water vapor condensation
- Ambient atmosphere: free from dust and aggressive fumes

**Production and distribution:**

**LABOR – ASTER**

Poland, 04-218 Warsaw, ul. Czechowicka 19

tel. +48 22 610 71 80 ; +48 22 610 89 45; fax. +48 22 610 89 48

e-mail: [biuro@labor-automatyka.pl](mailto:biuro@labor-automatyka.pl) [labor@labor-automatyka.pl](mailto:labor@labor-automatyka.pl) ; [http:// www.labor-automatyka.pl](http://www.labor-automatyka.pl)

The manufacturer reserves the right to make changes to the product.

Issue 07/2024

Table 1. Pt100

Range number	Range °C	Sensor's nonlinearity [%]
P1	0....25	+0.11
P2	0....40	+0.12
P3	0....60	+0.22
P4	0...100	+0.39
P5	0...120	+0.46
P6	0...150	+0.57
P7	0...200	+0.76
P8	0...250	+0.96
P9	0...300	+1.16
P10	0...400	+1.58
P11	0...550	+2.22
P12	50...150	+0.38
P13	100...320	+0.87
P14	100...400	+1.2
P15	200...320	+0.49
P18	200...400	+0.81
P17	300...550	+1.06
P18	-10... +40	+0.18
P19	-20... +20	+0.16
P20	-30... +60	+0.34
P21	-30.. +150	+0.69
P22	-100...+50	+0.62
P23	-220...+50	+1.37
Other ranges according to order		

Table 2. Ni100

Range number	Range °C	Sensor's nonlinearity [%]
N 1	0....25	-0.67
N 2	0....40	-1.1
N 3	0....60	-1.6
N 4	0...100	-2.8
N 5	0...120	-3.5
N 6	0...150	-4.5
N 7	50...150	-3.0
N 8	-10... +40	-1.4
N 9	-20... +20	-1.15
N 10	-30... +60	-2.5
N 11	-30.. +150	-5.2
Other ranges according to order		